



Spirent Test Module Support in TestCenter Software

Effective January 30, 2021, the following obsolete Spirent hardware will no longer be supported in the Spirent TestCenter system, including user interface and API.

Spirent TestCenter January 2021 software release (5.17 release) will be the last release which supports this hardware. **If customers wish to continue using these products, they must stay with January 2021 (5.17 or prior) release.**

Impacted Part Numbers

| Model Number | Description |
|------------------|--|
| GBT-4001A | 10GBASE-T PERSONALITY BOARD, 1-PORT |
| XEN-4001A | XENPAK 10GBE LAN/WAN PERSONALITY BOARD, 1-PORT |
| XFP-4001A | XFP 10GBE LAN/WAN PERSONALITY BOARD, 1 PORT |
| XTO-4001A | X2 10GBE LAN PERSONALITY BOARD, 1-PORT |
| DX-100G-F1 | HYPERMETRICS DX 40/100GBE CFP 1-PORT |
| DX-100G-F2 | HYPERMETRICS DX 40/100GBE CFP 2-PORTS |
| DX-100GO-F1 | HYPERMETRICS DX 100GBE ONLY CFP 1-PORT |
| DX-100GO-F2 | HYPERMETRICS DX 100GBE ONLY CFP 2-PORTS |
| DX-40G-F1 | HYPERMETRICS DX 40GBE ONLY CFP 1-PORT |
| DX-40G-F2 | HYPERMETRICS DX 40GBE ONLY CFP 2-PORTS |
| NG-100G-F2 | HYPERMETRICS NG 100G 40/100GBE CFP 2-PORTS |
| C50-KIT-17-START | C50 4-PORT 5/2.5/1/100M 3 WIFI NIC 2.4GHZ/5GHZ HW TIMING |
| XFP-4004A | XFP UNIPHY/OC-192 PERSONALITY BOARD, 1 PORT |
| MX-100GO-F2 | HYPERMETRICS MX 100GBE ONLY CFP 2-PORTS |
| FX-100G-F1 | HYPERMETRICS FX 40/100GBE CFP 1-PORT |
| FX-100G-F2 | HYPERMETRICS FX 40/100GBE CFP 2-PORTS |
| FX-100GO-F1 | HYPERMETRICS FX 100GBE ONLY CFP 1-PORT |
| FX-100GO-F2 | HYPERMETRICS FX 100GBE ONLY CFP 2-PORTS |
| FX-40G-F1 | HYPERMETRICS FX 40GBE ONLY CFP 1-PORT |

| | |
|-------------|---|
| FX-40G-F2 | HYPERMETRICS FX 40GBE ONLY CFP 2-PORTS |
| MX-100G-F1 | HYPERMETRICS MX 40/100GBE CFP 1-PORT |
| MX-100G-F2 | HYPERMETRICS MX 40/100GBE CFP 2-PORTS |
| MX-100GO-F1 | HYPERMETRICS MX 100GBE ONLY CFP 1-PORT |
| MX-40G-F1 | HYPERMETRICS MX 40GBE ONLY CFP 1-PORT |
| MX-40G-F2 | HYPERMETRICS MX 40GBE ONLY CFP 2-PORTS |
| MXP-10G-S2 | HYPERMETRICS MXP 10GBE SFP+ 2-PORTS |
| MXP-10G-S4 | HYPERMETRICS MXP 10GBE SFP+ 4-PORTS |
| MXP-10G-S8 | HYPERMETRICS MXP 10GBE SFP+ 8-PORTS |
| FX-100G-P2 | FX 100GBE ONLY CFP2 - 2-PORTS SINGLE SLOT |
| MX-100G-P2 | MX 100GBE ONLY CFP2 - 2-PORTS SINGLE SLOT |

What does this mean to Spirent Customers?

- Existing valid service agreements will be honored until expiration
- Existing and new (ALM) valid service hardware agreements will be honored
- Customers should consider upgrading to production released hardware
- Please note: this hardware has been discontinued for over three years and are all currently obsolete. During this period Spirent has not been implementing any hardware or software fixes, this will continue to be the case moving forward.
- Spirent does not accept repairs nor implement enhancements, bug fixes on discontinued or obsolete products. This has been the policy for above listed hardware for at least three years and will continue to be our policy going forward.

Please contact your Spirent Sales Representative with any questions.

